### **LMA District Cover Sheet**

### **Spring 2010 Levee Inspection Results**

## Sacramento Maintenance Yard East Levee Yolo Bypass

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				
	** Non-receipt of Su	ımmer or Winter Inspe	ection Reports may effec	ct overall annual rating.
FALL INSPECTIONS: The overall maintena	d using the same crite	ria in the spring and ir	the fall.	
Comments				

#### **Unit Cover Sheet**

### **Spring 2010 Levee Inspection Results**

## **Sacramento Maintenance Yard East Levee Yolo Bypass**

	vvaten	way		вапк	Unit Miles	
	Left	2.00				
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)	
Unit Maintenance Rating (Fall Only)						
Date of Inspection	3/23/2010 - 3/23/2010					
DWR Inspector	John Williamson					
Accompanied By						
Check one:						
project components conditions other that deficiencies identified.  During the current with project components maintenance and the following changes in the comment seemed.	<ul> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.</li> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.</li> <li>(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).</li> </ul>					
Comments						
One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to:  DWR Summer/Winter Inspection Reports 3310 El Camino Avenue, Room LL-30 Sacramento, CA 95821-9000						
X Signature of LMA Repres	sentative		Date			

#### Levee Inspection Report By Mile - Spring 2010

## Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.00	03/23/2010 03/23/2010	John Williamson

LMR	Levee	e Mile	Category	Item	Location	Rating	Action/Comment	GPS Latitud	e/Longitude	Issue No.
No.	Start	End	Calegory	пеш	tion	ing	Action/Comment	Start	End	Photo
1	0.01	2.00	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.765308 ° -121.635058 °	38.736112 ° -121.633679 °	1 Y
2	0.05	0.05	Earthen Levee	Encroachments	LS	М	Tree or limb	38.764820 ° -121.635328 °	38.764820 ° -121.635328 °	
3	0.09	2.00	Earthen Levee	Vegetation	ws	М	Control annual grass and weeds on the levee slopes and easements.	38.764094 ° -121.635518 °	38.736112 ° -121.633679 °	3 Y
4	1.64	2.00	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.741404 ° -121.634025 °	38.736112° -121.633680°	4 Y

\*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor

## Levee Inspection Report By Mile - Spring 2010

## Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.00	03/23/2010 03/23/2010	John Williamson

Levee Mile Report Line	1			
Start Levee Mile	0.01			
End Levee Mile	2.00			
Location	Land Side			
Category	Earthen Levee			
Item	Vegetation			
grasses mow or burn				
johngw_s_20100324_056.jpg				

Levee Mile Report Line	2			
Start Levee Mile	0.05			
End Levee Mile	0.05			
Location	Land Side			
Category	Earthen Levee			
Item	Encroachments			
remove cut tree limbs and brush from levee				

johngw\_s\_20100324\_058.jpg

Levee Mile Report Line	2			
Start Levee Mile	0.05			
End Levee Mile	0.05			
Location	Land Side			
Category	Earthen Levee			
Item	Encroachments			
remove cut tree limbs and brush				
johngw_s_20100324_059.jpg				







\*\* Rating

A : Acceptable PO : Parti.
M : Minimally Acceptable CO : Com
U : Unacceptable N : Not I

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor

### Levee Inspection Report By Mile - Spring 2010

# Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.00	03/23/2010 03/23/2010	John Williamson

Levee Mile Report Line	3			
Start Levee Mile	0.09			
End Levee Mile	2.00			
Location	Water Side			
Category	Earthen Levee			
Item	Vegetation			
grasses mow or burn				
johngw_s_20100324_057.jpg				

Levee Mile Report Line	4
Start Levee Mile	1.64
End Levee Mile	2.00
Location	Crown
Category	Earthen Levee
Item	Crown Surface /
	Depressions / Rutting
regrade crown and add A	B for all weather surface
johngw_s_20100324_060.jpg	



